

Su-27 Lisse 9T4 au décollage Pleine Charge PC

TPS DE MONTEE	MEILLEUR TEMPS DE MONTEE ISO Vi et ISO Mach															
ALTITUDE	ISO 300	ISO 360	ISO 420	ISO 480	ISO 540	ISO 600	ISO 660	ISO 720	ISO 780	ISO 840	M 0.80	M 0.85	M 0.90	M 0.95	M 1.00	M 1.05
1000	00:35	00:29	00:37	00:35	00:38	00:40	00:43	00:42	00:49	00:51	00:53	00:55	00:54	00:54	00:53	00:54
2000	00:44	00:47	00:52	00:49	00:51	00:51	00:56	00:51	00:58	00:59	01:01	01:03	01:05	01:11	01:10	01:13
3000	01:12	01:08	01:09	01:04	01:05	01:04	01:06	01:02	01:08	01:09	01:06	01:08	01:10	01:18	01:19	01:30
4000	01:39	01:29	01:28	01:21	01:20	01:19	01:19	01:13	01:19	01:18	01:12	01:14	01:16	01:24	01:26	01:45
5000	02:06	01:53	01:49	01:39	01:35	01:33	01:33	01:25	01:29	01:28	01:20	01:22	01:22	01:31	01:34	01:57
6000	02:36	02:18	02:12	01:59	01:54	01:49	01:47	01:37	01:40	01:41	01:28	01:28	01:29	01:38	01:40	02:05
7000	03:08	02:46	02:37	02:23	02:14	02:07	02:01	01:50	01:53	01:58	01:38	01:37	01:36	01:45	01:47	02:14
8000	03:47	03:17	03:06	02:49	02:36	02:25	02:17	02:05	02:09	02:16	01:49	01:47	01:46	01:54	01:55	02:24
9000	04:33	03:55	03:38	03:18	02:57	02:42	02:35	02:24	02:32	02:43	02:05	01:59	01:57	02:05	02:05	02:35
10000	05:25	04:36	04:18	03:53	03:20	03:01	02:54	02:48	02:59	03:07	02:22	02:13	02:08	02:17	02:17	02:45
11000	06:41	05:31	05:08	04:31	03:48	03:25	03:22	03:20	03:27	03:36	02:49	02:34	02:24	02:35	02:32	02:56
12000	08:27	06:56	06:20	05:09	04:23	04:00	04:01	03:55	04:01	04:12	03:29	03:05	02:49	02:55	02:52	03:13
13000	11:33	08:53	07:27	05:55	05:09	04:54	04:48	04:37	04:50	05:02	04:23	03:44	03:20	03:25	03:18	03:47
14000	17:17	11:31	08:24	06:59	06:09	05:53	05:41	05:28	05:45	06:05	05:49	04:40	04:01	04:03	04:00	04:14

